

FORMERLY "DEALER ONLY" PARTS

NEW TO THE AFTERMARKET

REAR DIFFERENTIAL BREATHER KIT

NEW TO THE AFTERMARKET



Allows pressure inside the differential to equalize with the atmospheric pressure

924-5213
Freightliner 2014-81
OE: KIT2902

FAILURE MODE:

- Tube clogs or lost.
- Failure results in blown seals or differential water contamination

STEERING SHAFT

LINE EXTENSION

OVER 5 SKUS AVAILABLE



Restores steering to proper function

DORMAN ENGINEERED - Double D design improved durability and eliminates clunking



425-5602
Chevrolet 2002-90, GMC 2002-90
OE: 26015359

FAILURE MODE:

- Clunking and/or binding in the steering column

HOOD RESTS

NEW TO THE AFTERMARKET



RUST

924-5222
Freightliner Century Class 2005-96
OE: A1713534001



RUST

924-5223
Freightliner Century Class 2005-96
OE: A1713534000

Provides support to the hood while the vehicle is operating

FAILURE MODE:

- Rust, corrosion
- Failure results in hood vibrating loudly and possibly cracking

HEATED MIRROR GLASS

LINE EXTENSION

4 SKUS AVAILABLE



955-5201
Freightliner Coronado
2011-08,
Spot Mirror
OE: A2259713001



955-5208
Freightliner Coronado
2011-08,
Full Length Mirror
OE: TL28531



955-5202
Freightliner Columbia 2011-02,
Freightliner M2 106 2011-03,
Freightliner M2 112 2011-08,
Spot Mirror
OE: TL28568



955-5203
Freightliner Columbia 2011-02,
Freightliner M2 106 2011-03,
Freightliner M2 112 2011-08,
Full Length Mirror
OE: A2258516001

Easy snap-on replacement

REDUCE REPAIR COST - Replace just the broken or missing mirror glass instead of the entire mirror assembly



FAILURE MODE:

- Mirror glass cracks

BE THE FIRST TO KNOW ABOUT FORMERLY "DEALER ONLY" PARTS!
Sign up at www.DormanHDSolutions.com/signup

CUSTOMER SERVICE:
1-800-523-2492